

Nickel-Plated Brass Adaptors

Nickel-plated brass	ØD	ØD1	C	٤	E	F	Κ	L	kg
		7	G1/8	0931 06 10	6	12	4	20	0.00
	6	7	G1/4	0931 06 13	8	14	5	20	0.01
	7	8	G1/8	0931 07 10	6	12	4	20	0.00
		8	G1/4	0931 07 13	8	14	5	20	0.0
		8	G3/8	0931 07 17	9	19	5	20	0.0
	8	9	G1/8	0931 08 10	6	12	4	20	0.0
		9	G1/4	0931 08 13	8	14	5	20	0.0
		9	G3/8	0931 08 17	9	19	5	20	0.0
	10	12	G1/4	0931 10 13	8	14	5	20	0.0
		12	G3/8	0931 10 17	9	19	5	20	0.0
		12	G1/2	0931 10 21	10	22	6	22	0.0
	15	17	G3/8	0931 15 17	9	19	6	24	0.0
	10	17	G1/2	0931 15 21	10	22	6	24	0.0
	18	20	G1/2	0931 18 21	10	22	6	24	0.0

Adaptors and Manifolds

legris 9-17



Adaptors, Plugs and Manifolds

Parker Legris offers a **wide range of adaptors and manifolds** compatible with the various Parker Legris fitting systems. This range of products provides the user with a **complete solution** covering numerous applications, both in non-corrosive and corrosive environments.

Product Advantages

Large Range & Flexibility	A complete offer, from the simple adaptor to a modular manifold solution			
,	Large selection of materials for excellent chemical compatibility: brass, steel, stainless steel, aluminium			
	Surface treatment for increased corrosion resistance: nickel-plated brass or anodised aluminium			
	Stainless steel for corrosive environments BSPP, BSPT, NPT and metric threads	Packaging Robotics		
Performance	Robust design Suitable for low to high pressure, depending on configuration and material Forged shapes for mechanical strength	Textile Pneumatics Automotive Process Food Process		

Technical Characteristics

Products		Manifolds			
Component Materials	Brass	Nickel-plated brass	Stainless steel 316L	Steel	Anodised aluminium
Working Pressure	1/8" to 1/2": 200 bar 3/4" and 1": 150 bar 1¼" to 2": 100 bar, without sealing washer	60 bar	1/8" to 1/2": 200 bar 3/4" and 1": 150 bar 1¼" to 2": 100 bar, without sealing washer	1/8" to 1/2": 200 bar 3/4" and 1": 150 bar 1¼" to 2": 100 bar, without sealing washer	20 bar
Working Temperature	-40°C to +150°C without sealing washer -20°C to +80°C with sealing washer	-10°C to +80°C	-20°C to +180°C	-10°C to +80°C	-10°C to +80°C

9-6 Clegris