



21 Diagnostic adapters SCA

Technical data and order codes



SCA-1/2-PQC



SCA-EMA-3/PQC

Parker diagnostic quick-connection coupling

Order code	PN	Pmax	Pburst	T1	L1	S1	S2
SCA-1/4-PQC	400 bar	600 bar	1,000 bar	1/4" BSPP	—	—	—
SCA-1/2-PQC	400 bar	600 bar	1,000 bar	1/2" BSPP	59	27	—
SCA-EMA-3/PQC	400 bar	600 bar	1,000 bar	M16x2	78	21	17



Note pressure ranges!

Adapters may only be used in connection with products listed in this catalog.

